

Shipping Log

An error has occurred while processing SubReport 'subReport2':
Unable to find the specified file.

Scan Criteria Work Order number: Company: Shipped date from: Shipped date to:
--

Part / Tool Number	Part / Tool Description	Serial Number	Qty	P.O. Number	Lot Number / Tool ID	Shipped to	Carrier	Waybill Number	Shipping
4020577-3 Shipped:	D/G 24-Oct-2007	90064639 Work Order:	1	PO07-00384.1		Duncan Aviation Lincoln			0.00 USD
		N650MG-416.1.1 #1						Type: Ship to Vendor O/S (PO07-00384.1)	
50-820130-8 Shipped:	EYE ASSY 24-Oct-2007	Work Order:	1	PO06-02626.20	LT06-01697	Raytheon	2287--2697-4	856905461840	0.00 USD
		N29PE-98.1.9 #20						Type: Ship Rejected Receipt to Source	
50-820130-2 Shipped:	EYE 24-Oct-2007	Work Order:	1	PO06-02626.23	LT06-01698	Raytheon	2287-2697-4	856905461840	0.00 USD
		N29PE-98.1.9 #23						Type: Ship Rejected Receipt to Source	
50-820103-5 Shipped:	YOKE- NOSE GEAR FITTING 24-Oct-2007	Work Order:	1	PO06-02626.26	LT06-01699	Raytheon	2287-2697-4	856905461839	0.00 USD
		N29PE-98.1.9 #26						Type: Ship Rejected Receipt to Source	
50-380177-5 Shipped:	Boost Pump 24-Oct-2007	3AW50 Work Order:	1	PO07-00164.1		Aviall			0.00 USD
								Type: Ship to Vendor O/S (PO07-00164.1)	
5010598 Shipped:	Nose Wheel Assembly N479PR 24-Oct-2007	JUN01-3646 Work Order:	1	PO07-00085.1		Aviall			0.00 USD
								Type: Ship to Vendor O/S (PO07-00085.1)	
5010598 Shipped:	Nose Wheel Assembly N479PR 24-Oct-2007	APR01-3488 Work Order:	1	PO07-00085.2		Aviall			0.00 USD
								Type: Ship to Vendor O/S (PO07-00085.2)	
3019906 Shipped:	Fuel Flow Divider 18-Jul-2006	2495 Work Order:	1			Kansas Aviation	FEDEX	856905461758	0.00 USD
								Type: Unexpected Shipment	
Please find fuel flow divider shipped for overhaul, and associated paperwork.									
If you have any questions please call Sean Comstock at 630-587-9550									
284182 Shipped:	Seat Base 28-Jul-2006	Unknown Work Order:	1			Aviation Fabricators	FEDEX	856905461780	0.00 USD
								Type: Unexpected Shipment	
Here is another Seat Base that we would like to have repaired. Your loaner unit is still installed on the aircraft.									
If you have any questions please call Sean Comstock at 630-587-9550									